								N	EMSA/TS	&IS/0007						
MONTHLY RETURNS ON ACCIDENT INVESTIGATED																
ARE	AREA INSPECTORATE FIELD OFFICE: IBADAN															
S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/O CCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
	04/08/2019	ELECTRICAL	ELECTROCUT		IBEDC	IBEDC	8-4-2019/ 6-	1	NIL	THE VICTIM (A	NEMSA, IBADAN	THE VICTIM	INVESTIGAT	MR. OMOJOLA	INVESTIGATION	STAFF WORKING ON HT
		(FATAL)	ION	GOLF			4-2019			STAFF OF IBEDC)	OFFICE	HAD A	ION	(IBEDC STAFF &	ONGOING	LINES SHOULD THAT IN
				COURSE						WAS WORKING ON		DIRECT		TEAM LEADER		ADDITION TO TAKING
				CLUB,						A 33kV LINE WHEN		CONTACT		AT THE SCENE		OUTAGE ON THE LINE,
				ONIREKE,						HE RECEIVED		WITH AN		OF THE		THEY SHOULD: 1.
				IBADAN						ELECTRIC SHOCK		ENERGIZED		INCIDENT		ENSURE USE OF
										AND DIED AS A		CONDUCTO				COMPLETE PPE 2.
										RESULT		R DUE A				GROUND THE LINE THEY
												MOMENTAR				ARE WORKING ON 3.
												Υ				MAINTAIN A MINIMUM
												ELECTRICAL				SAFE CLEARANCE
												INDUCTION				BETWEEN OVERHEAD
												FROM				CONDUCTORS ON
												ONIREKE				DIFFERENT CIRCUIT
1												11KV LINE.				

PLEASE SEE PICTURES ATTACHED