


INSPECTORATE FIELD OFFICE:		JOS		MONTH:MARCH 2019	
S/N	Date of Investigation	Accident Description	Accident Type	Location	Company
1	8TH&11TH MARCH,2019	ELECTROCUTION OF 3 PERSONS AT UBA NEW BRANCH DADIN KOWA JOS SOUTH LGA PLATEAU STATE	ELECTROCUTION	UBA NEW BRANCH DADIN KOWA JOS SOUTH LGA PLATEAU STATE	UBA

TEMPLATE FOR MONTHLY R

Reported By	DATE REPORTED/ OCCURRED	FATALITIES	INJURIES
ENGR PATRICK DALAHOL	7TH/5TH MARCH,2019.	3	2

RETURNS ON ACCIDENT INVESTIGATED

Historical Incident (If Any)	Pictures	Investigated By	Possible Root Causes
M		ENGR G.D NANJWAN, ENGR D.D BABA, STEPHEN DINJU & MUHAMMAD USMAN JAMILU	HIGH IMPEDANCE FAULT DUE TO NEGLIGENCE AND LACK OF SAFETY KNOWLEDGE AT WORK

Actions Taken	Details of eye witnesses (Contacts)	Follow Up Actions (Date) & outcome	Recommendations made to eliminate surface & root causes
<p>ENGAGED THE CONTRACTOR ON SAFETY TIPS WHILE AT WORK</p>	<p>UBA BRANCH MANAGER,NESCO STAFF,CONTRACTOR,NPF ETC</p>	<p>POSSIBLE LINE RELOCATION BEEN NEGOTIATED WITH THE DISCO</p>	<p>LINE SHOULD BE RELOCATED,SAFETY TIPS WHILE AT WORK THOUGHT TO WORKERS,INCRESED SENSITIZATION ABOUT DANGERS OF WORKING AROUND LIVE POWERLINE</p>