

**NEMSA/TS&IS/0007**

**MONTHLY RETURNS ON ACCIDENT INVESTIGATED FOR MAY, 2019**

**AREA INSPECTORATE FIELD OFFICE: IFO, KANO**

S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
1	06/03/2019	A nine year old boy	Electrocution	Gaida Makad	Kedco	HSE, Kedco	30/5/2019/26/		1 NIL	one incident occurred	Engr. M.G.M. Kor	Undersize ser	Visited the s	Two eyewitnesses	I went back the follo	1. All untreated wooden poles in the localities should be replaced with concrete poles; 2. All undersize service wires used in different houses and those use as LT networks should be re-conducted with 16mm <sup>2</sup> and 70mm <sup>2</sup> respectively; 3. Rated fuses should be use in the feeder pillar instead of strands of copper wire; 4. The substation flour require gravelling.
2																

16

17

*PLEASE SEE PICTURES ATTACHED*

19

20