


AREA FIELD OFFICE:		OWERRI		MONTH:	
S/N	Date of Investigation	Accident Description	Accident Type	Location	DisCo
1	29th MARCH 2019	A 56 years old woman, Mrs Chitolu Tomas was Electrocutted as the jumper wire of existing 11KV GRA feeder line spanned	ELECTROCUTION	OKPARA SQUARE, UMUAHIA, Abia state.	EEDC

Mar-19

Reported By	DATE REPORTED/ OCCURRED	FATALITIES	INJURIES
Local news report on 29/3/2019.	29th / 28th MARCH 2019	1	1

Historical Incident (If Any)	Pictures	Investigated By	Possible Root Causes
<p>The 56 years old woman (the victim), according to the eye witness report, hailed from Umuokehi Ohuhu in Umuahia North Local Government. One of her children Friday</p>		<p>ENGR. K.O. IKPO (NEMSA): KINGSLEY OGBODO (NEMSA): ENGR. OZOEZE ONYEBUCHI: ENGR. FRANCIS IWU (HEAD HSE FEDC):</p>	<p>Jumper wire cut of existing 11kV line dropping on a stay wire; energized the stay structure. The victim, Mrs Chitolu Thomas, made direct body contact with</p>





Actions Taken	Details of eye witnesses (Contacts)	Follow Up Actions (Date) & outcome	Recommendations made to eliminate surface & root causes
VISITED SITE, INVESTIGATED THE COURSE OF ACCIDENT, SENT REPORT TO APPROPRIATE AUTHORITY FOR COMPLIANCE.	On condition of anonymity, two persons, also road side traders, explained that the deceased was serving the canteen owner. The latter had finished the day's	Visited the site of accident on 29/3/2019, confirmed that the jumper line of 11KV network that snapped and fell on stay wire causing	1. Double poles to be installed at the tee off angular point. 2. Steel cross arms to be solidly earthed. 3. Whole appropriate sizes of wires to be used to replace jointed pieces used for replacement during repairs. 4.