



# "SAFETY RANKING OF DISCOS & TCN IN THE POWER SECTOR" OCTOBER 2017 RANKING

at the

The Honourable Minister of Power, Works & Housing's

Monthly Sectoral Meeting with Operators of The Power Sector

on 13th October, 2017

Host: Benin Electricity Distribution Company (BEDC)

Venue: 330/132/33kV Transmission Substation, Asaba, Delta State

by

Engr. Peter .O. Ewesor

Managing Director/CEO &

Chief Electrical Inspector of the Federation





# Electrocutions in October 2017 still high at I

Accidents continue to occur because many Discos fail to

implement NEMSA's Recommendations. Sanctions may be

applied on such Discos going forward.

 Discos' efforts on disconnection / removal of structures/buildings/premises under power supply lines to

be intensified.

NEMSA No. 4, Dar es Salaam Crescent Off Aminu Kano Crescent, Wuse II, Abuja, Nigeria.

· Discos' efforts at sensitization of the Public on using





#### Many of the accidents that occur in the power sector

#### can be attributed to seven (7) major factors:

(a) System
Protection
Equipment
Failures;

(d) Poor Response to Monitored Networks & use of substandard materials.

(g) Vandalism

(b) In some cases, total absence of protection devices.

(c) Poor Terminations , poor maintenance of Ageing Networks, Right-of-way issues. (e) Non adherence to safety rules, and regulations.

(f) Inadequate knowledge and Ignorance on the part of operators/consumers/publi

Operators of the Power Sector to address these points

urgently





#### **RANKING CRITERIA**

DESCRIPTION	EVENT	SCORES
I. TOTAL ACCIDENTS	NOT SCORED	NOT SCORED
II. NO. OF FATALITIES	0	40
III. NO. OF MAJOR INJURIES	0	25
IV. NO. OF BAD NETWORKS RESOLVED	>9	25
V. REPORTING COMPLIANCE	4	10
		100

Response	Scores
4	10
3	8
2	6
1	4
0	0

Fatalities (Deaths)				
No. of Fatalities	Scores			
0	40			
1 - 2	32			
3 – 4	24			
5-6	16			
7 – 8	8			
9 & Above	0			

#### 2015 BASELINE STUDY: Average Deaths/month = 9.5 (10)

<u>Ma</u> j	or	<u>Inj</u>	uri	<u>es</u>	
£ D.					ĺ

Major Injuries	Scores
0	25
1 – 2	20
3 – 4	15
5 – 6	10
7 – 8	5
9 & Above	0

2015 BASELINE STUDY: Not Available

#### **NETWORK RESOLVED**

No. Resolved	Scores
9 & Above	25
7 – 8	20
5-6	15
3 – 4	10
1 - 2	5
0	0

2015 BASELINE STUDY: Average/ month = 7.5 (8)

# To be revised upwards



**RAW DATA** 

**MONTH: OCTOBER 2017** 

WEIGHTED SCORE

S/No.	DISCO	TOTAL ACCIDENTS WITH DEATHS	DEATHS [STAFF	NO. OF MAJOR INJURIES	NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	REPORTING COMPLIANCE
1	ABUJA	1	1	0	38	4
2	BENIN	0	0	0	24	4
3	EKO	1	1	1	17	4
4	ENUGU	0	0	1	49	4
5	IBADAN	0	0	0	6	4
6	IKEJA	0	0	0	88	4
7	JOS	2	2	0	62	4
8	KADUNA	0	0	0	9	4
9	KANO	1	1	0	25	4
10	PORT HARCOURT	1	2	0	4	4
11	YOLA	0	0	0	8	4
12	TCN	0	0	0	0	4
	TOTAL	6	7	2	330	

	JUNE								
DEATHS [STAFF & 3RD PARTY]	MAJOR INJURIES	BAD NETWORKS RESOLVED	REPORTING COMPLIANCE	TOTAL	RANKING				
32	25	25	10	92	3				
40	25	25	10	100	1				
32	20	25	10	87	5				
40	20	25	10	95	2				
40	25	15	10	90	4				
40	25	25	10	100	1				
32	25	25	10	92	3				
40	25	25	10	100	1				
32	25	25	10	92	3				
32	25	10	10	77	6				
40	25	20	10	95	2				
40	25	0	10	75	7				

Note: Discos should rectify defective networks reported to them by NEMSA as a priority.

This is because claims of self rectified networks by Discos have been found to be untrue/false.

Notification by Discos to NEMSA for verification should be weekly, rather than waiting till end of the month.






#### DISCOS & TCN RANKING TREND IN 2017

S/N o.	DISCO	JAN	FEB	MARCH	APRIL	MAY	JUNE	JULY	AUG	SEPT	ОСТ	NOV	DEC	YTD
1	ABUJA	1	4	1	8	6	6	6	2	2	3			7
2	BENIN	4	3	7	1	3	1	1	1	1	1			3
3	ЕКО	6	1	1	2	1	3	1	2	1	5			3
4	ENUGU	1	1	1	3	1	2	3	1	1	2			1
5	IBADAN	6	2	3	5	4	3	3	3	4	4			6
6	IKEJA	1	1	5	1	1	3	2	1	1	1			2
7	JOS	5	1	6	3	4	2	1	3	2	3			4
8	KADUNA	3	7	10	6	2	3	1	1	5	1			7
9	KANO	2	4	4	4	4	4	4	2	3	3			5
10	PORT HARCOURT	1	5	2	9	2	1	3	4	1	6			5
11	YOLA	1	6	9	7	1	1	1	1	1	2			4
12	TCN	6	8	8	7	5	5	5	5	6	7			7





#### CUMULATIVE DISCOS & TCN FATALITIES JANUARY - OCTOBER







#### **YEAR 2017 CUMULATIVE STATISTICS**

MONTH JANUARY – AUGUST 2017	TOTAL NO. OF ACCIDENTS WITH FATALITIES	TOTAL N FATALIT & 3RD P	IES [STAFF	NO. OF ACCIDENTS WITH ONLY INJURIES	NO. OF F		NO. OF EXPLOSIONS / FIRES	NO. OF VEHICULAR ACCIDENTS	NO. OF ENVIRONMENTAL ACCIDENTS	TOTAL LOST MAN- HOURS	NO. OF BAD NETWORKS REPORTED FOR THE MONTH	YEAR-TO- DATE NO. OF BAD NETWORKS REPORTED	YTD NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	RESPONSE TO NEMSA REPORTS IN WEEKS
		STAFF	3 <sup>RD</sup> PARTY		STAFF	3 <sup>RD</sup> PARTY								
ABUJA	19	0	23	8	3	9	0	2	0				905	
BENIN	7	1	6	0	0	0	0	0	0				230	
ЕКО	3	1	2	1	1	0	0	0	0				116	
ENUGU	3	2	1	1	1	0	0	0	0				300	
IBADAN	11	0	11	5	3	2	0	0	0				119	
IKEJA	2	1	1	10	9	2	5	21	3				863	
JOS	11	6	7	6	5	1	0	0	0				408	
KADUNA	6	2	4	3	2	1	1	0	0				83	
KANO	13	0	15	9	3	11	0	1	0				135	
PORT HARCOURT	6	0	14	2	1	10	0	0	0				148	
YOLA	4	1	3	1	0	1	0	0	0				121	
TCN	1	1	0	1	4	0	6	1	1				0	
YEAR TOTAL	86	15	87	47	32	37	12	25	4	製造			3428	





# Operators of the Power Sector to once again note that the target is ZERO Electrocutions

Discos to intensify efforts at:

(i) revamping their Protection schemes & equipment

(ii) rectifying their defective

YEAR	TOTAL NETWORK RECTIFIED
2014	199
2015	87
2016	801
2017	3428

to prevent electrical accidents and Also Discos should educate the general public or thice technical losses. need for extreme caution with using electricity!







Metallic Cradle Guard installed at a street in Benin City needs adequate earthing.





Unprotected substation at Kwanan Bukari, opposite Gwauron Gida, Katsina.





#### SAFETY TIPS

- Avoid contact with electric poles, Tv antenna poles, conductors and other electrical equipment installed in the open.
- Avoid staying under trees with conductors running over such trees.
- Avoid climbing masts constructed close to power lines. Avoid power cables and metallic objects.
- Wear rubber sole shoes always when on wet grounds.
- Report any fallen electric poles or conductors to the nearest electricity utility company or to NEMSA office nearest to you. Do not attempt to touch these.



