



"SAFETY RANKING OF DISCOS & TCN IN THE POWER SECTOR" MAY 2019 RANKING

by

Engr. Peter .O. Ewesor

Managing Director/CEO &

Chief Electrical Inspector of the Federation





Many of the accidents that occur in the power industry can be attributed to these major factors:

(i) System Protection Equipment Failures; (iv) Poor Response to Monitored Networks & use of substandard materials.

(vii) Vandalism

(ii) In some cases, total absence of protection devices. (v) Non adherence to safety rules, and regulations.

(iii)Poor Terminations
, poor maintenance of
Ageing Networks,
Right-of-way issues.

(Vi) Inadequate knowledge and Ignorance on the part of operators/consumers/public.

Operators of the Power Sector to address these urgently.





REVISED RANKING CRITERIA

DESCRIPTION	EVENT	SCORES
I. TOTAL ACCIDENTS	NOT SCORED	NOT SCORED
II. NO. OF FATALITIES	0	40
III. NO. OF MAJOR INJURIES	0	20
IV. NO. OF BAD NETWORKS RESOLVED	>21	30
V. STRUCTURES UNDER RIGHT-OF-WAY REMOVED	>20	5
VI. REPORTING COMPLIANCE	4	5
TOTAL		100

<u>Fatalities (Deaths)</u>							
Scores							
40							
20							
0							

2015 BASELINE STUDY:	
Average Deaths/month = 9.5 (10)	

- rajor mjarros	
No. of Persons with Major Injuries	Scores
0	20
1 – 2	15
3 – 4	10
5 – 6	5
7 & Above	0

Major Injuries

Structures under Right-of-Way Disconnected

Structures under Right-of-Way removed	Scores
21 & Above	5
11 – 20	3
5 – 10	1
Below 5	0

NETWORK RESOLVED

No. Resolved	Scores
21 & Above	30
16 – 20	20
11– 15	10
1-10	5
0	0
2015 BASE	LINE STUDY:

REPORTING COMPLIANCE

Average/month = 7.5(8)

Response	Scores
Within 1 week	5
Within 2 weeks	4
Within 3 weeks	3
Within 4 weeks	2
0	0



(NEMSA)

RAW DATA

MONTH: MAY, 2019

WEIGHTED SCORE

S/No.	DISCO		TOTAL NO. OF DEATHS [STAFF & 3RD PARTY]	MAJOR	NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	STRUCTURES UNDER RIGHT OF WAY DISCONNECTED	REPORTING COMPLIANCE
1	ABUJA	4	4	0	43	0	4
2	BENIN	1	1	0	12	10	4
3	EKO	0	0	0	15	46	4
4	ENUGU	0	0	0	41	3	4
5	IBADAN	0	0	0	12	27	4
6	IKEJA	1	1	1	10	0	4
7	JOS	1	1	0	11	6	4
8	KADUNA	1	2	0	8	0	4
9	KANO	1	1	0	32	0	4
10	PORT HARCOURT	0	0	0	2	0	4
11	YOLA	0	0	0	12	0	4
12	TCN	0	0	0	0	0	4
	TOTAL	9	10	1	198	92	

DEATHS [STAFF & 3RD PARTY]	MAJOR INJURIES	BAD NETWORKS RESOLVED	STRUCTURES UNDER RIGHT OF WAY DISCONNECTED	REPORTING COMPLIANCE	TOTAL	RANKING
0	20	30	0	5	55	7
20	20	10	1	5	56	6
40	20	10	5	5	80	2
40	20	30	0	5	95	1
40	20	10	5	5	80	2
20	15	5	0	5	45	9
20	20	10	1	5	56	6
20	20	5	0	5	50	8
20	20	30	0	5	75	3
40	20	5	0	5	70	4
40	20	10	0	5	75	3
40	20	0	0	5	65	5

Note: Discos should rectify defective networks reported to them by NEMSA as a priority.

Notification by Discos to NEMSA for verification should be weekly, rather than waiting till end of the month.



Compliance Record on Disconnection of Structures/Premises under or within Right-of-Way of Power Lines May 2019

S/No.	DISCO	TOTAL PREMISES/STRUCTURES DISCONNECTED	TOTAL PREMISES/STRUCTURES DEMOLISHED	RANKING
1	ABUJA	0	0	LAST
2	BENIN	10	0	3
3	EKO	46	0	1
4	ENUGU	3	0	5
5	IBADAN	27	0	2
6	IKEJA	0	0	LAST
7	JOS	6	0	4
8	KADUNA	0	0	LAST
9	KANO	0	0	LAST
10	PORT HARCOURT	0	0	LAST
11	YOLA	0	0	LAST
	TOTAL	92	0	

Notes:

- 1. Compliance by Discos to disconnect premises/buildings/structures under and within right-of-way of power lines has been unsatisfactory.
- 2. Discos are to note that they will be liable should electrical accidents occur in premises/buildings/structures which are under and/or within right-of-way of power lines and which the Discos are supplying electricity to.





Compliance Record on Disconnection of Structures/Premises under or within Right-of-Way of Power Lines January — May 2019

S/No.	DISCO	JAN	FEB	MAR	APR	MAY	TOTAL
1	ABUJA	0	0	0	0	0	0
2	BENIN	10	10	10	8	10	48
3	EKO	0	29	0	0	46	75
4	ENUGU	0	1	1	4	3	9
5	IBADAN	5	0	13	51	27	96
6	IKEJA	0	0	0	0	0	0
7	Jos	26	7	15	4	6	58
8	KADUNA	0	0	0	0	0	0
9	KANO	0	0	0	0	0	0
	PORT HARCOURT	0	0	0	0	0	0
11	YOLA	0	0	0	0	0	0
	TOTAL	41	47	39	67	92	286

Notes: TOTAL PREMISES/STRUCTURES DISCONNECTED

- 1. Compliance by Discos to disconnect premises/buildings/structures under and within right-of-way of power lines has been unsatisfactory.
- 2. Discos are to note that they will be liable should electrical accidents occur in premises/buildings/structures which are under and/or within right-of-way of power lines and which the Discos are supplying electricity to.





DISCOS & TCN RANKING TREND IN 2019

S/N o.	DISCO	JAN	FEB	MARCH	APRIL	MAY	JUNE	JULY	AUG	SEPT	ОСТ	NOV	DEC	YTD
1	ABUJA	5	3	4	5	8								9
2	BENIN	1	1	2	3	3								3
3	ЕКО	3	1	1	1	2								1
4	ENUGU	4	1	2	3	1								4
5	IBADAN	1	2	1	6	2								5
6	IKEJA	6	1	3	1	9								7
7	JOS	1	1	5	8	7								8
8	KADUNA	1	1	1	4	4								4
9	KANO	1	1	1	3	4								3
1(1)	PORT HARCOURT	1	2	3	2	5								6
11	YOLA	2	1	1	1	4								2
12	TCN	6	4	6	7	6								10







Operators of the Power Sector should aim to achieve Zero target for Electrocutions & Injuries nationwide.

Discos are encouraged to report domestic electrocutions not directly connected with their networks, for information only. This will not count against their ranking.

Discos to intensify efforts at:

- (i) revamping/calibrating their protection schemes & equipment
- (ii) rectifying defective networks to prevent electrical accidents and reduce technical losses.
- [iii] educating the general public on the need for extreme caution with using electricity!





SAFETY TIPS

- Do not build structures or carry out activities under power lines
- Avoid contact with electric poles, Tv antenna poles, conductors and other electrical equipment installed in the open.
- Avoid staying under trees with conductors running over such trees.
- Avoid climbing masts constructed close to power lines.
- Avoid power cables and metallic objects.
- Wear rubber sole shoes always when on wet grounds.
- Report any fallen electric poles or conductors to the nearest electricity utility company or to NEMSA office nearest to you. Do not attempt to touch these.

Work Safely! Safety First - Safety Always - NEMSA.