

TS&IS/0007

MONTHLY RETURNS ON ACCIDENT INVESTIGATED FOR THE MONTH OF AUGUST, 2019

AREA INSPECTORATE FIELD OFFICE: EKO ZONAL OFFICE

S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
1	23RD - 25TH AUGUST, 2019	ELECTRICAL ACCIDENTS / ELECTROCUTION INVOLVING THREE INJURIES AND ONE DEATH AROUND 9AM	ELECROCUTION / ELECTRICAL ACCIDENTS	68, BANKOLEMOH STREET, SURULERE, LAGOS	EKO	MD/ CEO & CEIF	18TH, AUGUST 2019	ONE	THREE	NIL	ENGR, OWAN D.E. ; ENGR. ITODO E.E & MUSA, WALIU	AGED/WEAK/EXPIRED SERVICE WIRES Routed over A METAL GATE	AN INVESTIGATION OF THIS INCIDENT WAS CARRIED OUT & REPORT COMPILED AND SENT TO NEMSA HQ & EKEDC	MR. TOYIN GIWA (08055061751) MISS DAMITOLA & MR OLOYEDE QUADRI	NIL	1. FEEDER PILLAR UNITS SHOULD BE REPLACED 2. SERVICES WIRES SHOULD BE PROPERLY Routed AND TRUNKED ON SEPARATE PHASES IN THE FEEDER PILLAR 3.N EUTRAL WIRES SHOULD BE TERMINATED ON DESIGNATED NEUTRAL LINK IN THE FEEDER PILLAR UNIT 4. PROPER PROTECTIVE EARTHING SHOULD BE PROVIDED FOR THE AFFECTED

16

17

PLEASE SEE PICTURES ATTACHED

19

20