

AREA FIELD OFFICE:		SOKOTO		MONTH:	
S/N	Date of Investigation	Accident Description	Accident Type	Location	DisCo
1	15/04/2019	Electrical fire accident at Simple 7 supermarket, Sokoto	Electrical	Abdullahi Fodio Road, Sokoto	KAEDCO

TEMPLATE FOR MONTHLY R

**APRIL, 2019**

Reported By	DATE REPORTED/ OCCURRED	FATALITIES	INJURIES
Area Inspecting Engineer	14/04/2019	NILL	NILL

## RETURNS ON ACCIDENT INVESTIGATED

---

Historical Incident (If Any)	Pictures	Investigated By	Possible Root Causes
NONE	NONE	Area Inspecting Engineer and other technical staff	Power surge

Actions Taken	Details of eye witnesses (Contacts)	Follow Up Actions (Date) & outcome	Recommendations made to eliminate surface & root causes
Visit to the site and carryout investigation with report to avoid future occurences	Malam Garba Mohammed. Manager Simple 7 Supermarket, Abdullahi Fodio Road, Sokoto	Ensure the observations and recommendations were effected	<ol style="list-style-type: none"> <li>1. Ensure the earth conductor of the transformer body is change to acceptable size.</li> <li>2. Ensure a competent electrician with NEMSA registration is employed for wiring.</li> <li>3. All the protective devises should be put in place</li> </ol>