	ND45A/T5AD5/0007														
MONTHLY RET	MONTHLY STEWS ON MODERAT INVIDIGATED														
S/N DAT	E OF ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO REP	ORTED BY R	DATE SPORTEDY FATALITIES ECLIPSED	S INJURIES HISTORICAL INCIDENT (If Any	INVESTIGATED POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EVE WITNESSES (CONTACTS)	FOLIOWALP ACTIONS (DATE) & OUTCOME	ISCOMMUNICATIONS MAKES TO CLIMINATE SURFACE & MODE CAUSES			
1 15/07/2	019 ROOFING A NEW BUILDING NEAR 11KV UNE	RECTROCUTION	NEAR TARGET ILINCTION ALONG ATIKU ABUBAKAR WAY IIMETA	YEDC IMFO	DRMANT 13	N07/2019	1 1 NL	NEMSA TEAM HUMAN ERRORINGGUIGENCEIAND PROTECTION FAILURE AT THE DISCO	PUBLIC ENLIGHTEMENT	JULIUS NEMPHASIDES 72722 2091 (ZUNNA OKONEJO7056996032)	VISIT TO THE ACCIDENT SCENE	PROPRIS SHOULD NOT ENDROGON WITO THE REGHT OF WAY OF HIGH TENSION PROPRIS SHOULD BE DAUGHTEND TO APPROACH DISCOS IF THEY ARE TO WORK UNDER OR NEAR HIGH TENSION LINES AND THE DISCOS SHOULD IMPROVE THOSE PROTECTION MEASURE.			
2											1				

PLEASE STO PERMIT ATTACKED

