

(NEMSA)



"SAFETY RANKING OF DISCOS & TCN IN THE POWER SECTOR"

AUGUST 2017 RANKING

at the The Honourable Minister of Power, Works & Housing's

Monthly Sectoral Meeting with Operators of The Power Sector

on 11th September, 2017

Host: Eko Electricity Distribution Company (EKEDP)

Venue: TCN Akangba Transmission Station, Adelabu, Surulere, Lagos

by

Engr. Peter .O. Ewesor Managing Director/CEO & Chief Electrical Inspector of the Federation





Electrocutions in August 2017 still high at - 8 fatalities.

- Discos' efforts on disconnection / removal of structures/buildings/premises under power supply lines to be intensified.
- State governments collaboration essential for its success.

NEMSA No. 4, Dar es Salaam Crescent, Off Aminu Kano Crescent, Wuse II, Abuja, Nigeria. www.nemsa.com.ng





Many of the accidents that occur in the power sector

can be attributed to seven (7) major factors:

(a) System Protection Equipment Failures; (d) Poor Response to Monitored Networks & use of substandard materials.

(b) In some cases, total absence of protection devices.

> (c) Poor Terminations, poor maintenance of Ageing Networks, Right-of-way issues.

(g) Vandalism

(e) Non adherence to safety rules, and regulations .

> (f) Inadequate knowledge and Ignorance on the part of operators/consumers/public.

Operators of the Power Sector to address these points urgently.



(NEMSA)



RANKING CRITERIA

DESCRIPTION	EVENT	SCORES
I. TOTAL ACCIDENTS	NOT SCORED	NOT SCORED
II. NO. OF FATALITIES	0	40
III. NO. OF MAJOR INJURIES	0	25
IV. NO. OF BAD NETWORKS RESOLVED	>9	25
V. REPORTING COMPLIANCE	4	10
		100

Response	Scores
4	10
3	8
2	6
1	4
0	0

Fatalities (Deaths)								
No. of Fatalities Scores								
0	40							
1 - 2	32							
3 – 4	24							
5 – 6	16							
7 – 8	8							
9 & Above	0							

2015 BASELINE STUDY: Average Deaths/ month = 9.5 (10)

Major Injuries									
No. of Persons with Scores Major Injuries									
0	25								
1 – 2	20								
3 – 4	15								
5 – 6	10								
7 – 8	5								
9 & Above 0									
2015 PASELINE STUDY.									

2015 BASELINE STUDY: Not Available

NETWORK RESOLVED									
No. Resolved	Scores								
9 & Above	25								
7 – 8	20								
5 – 6	15								
3 – 4	10								
1 - 2	5								
0	0								

2015 BASELINE STUDY: Average/ month = 7.5 (8)





(NEMSA)



NE	MSA 🏽						-					🚑 🎑 i
× *	ENCY *	AW DATA		MO	NTH: /	GHTED)					
S/No.	. DISCO	ACCIDENTS WITH	TOTAL NO. OF DEATHS [STAFF & 3RD PARTY]	NO. OF MAJOR INJURIES	NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	REPORTING COMPLIANCE	DEATHS [STAFF & 3RD PARTY]		BAD NETWORKS RESOLVED	REPORTING COMPLIANCE	TOTAL	RANKING
1	ABUJA	2	2	0	24	4	32	25	25	10	92	2
2	BENIN	0	0	0	25	4	40	25	25	10	100	1
3	EKO	1	1	0	13	4	32	25	25	10	92	2
4	ENUGU	0	0	0	19	4	40	25	25	10	100	1
5	IBADAN	2	2	1	13	4	32	20	25	10	87	3
6	IKEJA	0	0	0	211	4	40	25	25	10	100	1
7	JOS	1	1	2	63	4	32	20	25	10	87	3
8	KADUNA	0	0	0	16	4	40	25	25	10	100	1
9	KANO	1	1	0	10	4	32	25	25	10	92	2
10	PORT HARCOURT	1	1	0	10	4	32	25	5	10	72	4
11	YOLA	0	0	0	34	4	40	25	25	10	100	1
12	TCN	N/A	N/A	N/A	N/A	N/A	0	0	0	0	0	5
	TOTAL	8	8	3	438							

Note: Discos should rectify defective networks reported to them by NEMSA as a priority. This is because claims of self rectified networks by Discos have been found to be untrue/false. Notification by Discos to NEMSA for verification should be weekly, rather than waiting till end of the month.



(NEMSA)



YEAR 2017 CUMULATIVE STATISTICS

MONTH JANUARY – AUGUST 2017	TOTAL NO. OF ACCIDENTS WITH FATALITIES	TOTAL N FATALIT & 3RD P	IES [STAFF	NO. OF ACCIDENTS WITH ONLY INJURIES	NO. OF F INJURED		NO. OF EXPLOSIONS / FIRES	NO. OF VEHICULAR ACCIDENTS	NO. OF ENVIRONMENTAL ACCIDENTS	TOTAL LOST MAN- HOURS	NO. OF BAD NETWORKS REPORTED FOR THE MONTH	YEAR-TO- DATE NO. OF BAD NETWORKS REPORTED	YTD NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	RESPONSE TO NEMSA REPORTS IN WEEKS
		STAFF	3 RD PARTY		STAFF	3 RD PARTY								
ABUJA	18	0	22	7	2	9	0	2	0				1138	
BENIN	7	1	6	0	0	0	0	0	0				182	
EKO	2	1	1	0	0	0	0	0	0				85	
ENUGU	3	2	1	0	0	0	0	0	0				173	
IBADAN	10	0	10	5	3	2	0	0	0				98	
IKEJA	2	1	1	8	8	1	5	19	3				678	
JOS	9	5	6	4	3	1	0	0	0				289	
KADUNA	4	2	2	3	2	1	1	0	0				79	
KANO	10	0	12	9	3	11	0	0	0				90	
PORT HARCOURT	5	0	12	2	1	10	0	0	0				142	
YOLA	4	1	3	1	0	1	0	0	0				94	
TCN	1	1	0	1	4	0	5	1	0				0	
YEAR														
TOTAL	75	14	76	40	26	36	11	22	3	they.			3048	

Awaiting Final Verification



(NEMSA)



A	DISCOS & TCN RANKING TREND IN 2017													
S/N o.	DISCO	JAN	FEB	MARCH	APRIL	MAY	JUNE	JULY	AUG	SEPT	ОСТ	NOV	DEC	YTD
1	ABUJA	1	4	1	8	6	6	6	2					10
2	BENIN	4	3	7	1	3	1	1	1					4
3	ЕКО	6	1	1	2	1	3	1	2					3
4	ENUGU	1	1	1	3	1	2	3	1					1
5	IBADAN	6	2	3	5	4	3	3	3					8
6	IKEJA	1	1	5	1	1	3	2	1					2
7	JOS	5	1	6	3	4	2	1	3					5
8	KADUNA	3	7	10	6	2	3	1	1					9
9	KANO	2	4	4	4	4	4	4	2					7
10	PORT HARCOURT	1	5	2	9	2	1	3	4					6
11	YOLA	1	6	9	7	1	1	1	1					6
12	TCN	6	8	8	7	5	5	5	5					11





Operators of the Power Sector to once again note that the target is ZERO Electrocutions nationwide.

Discos to make more efforts to rectify their defective networks and educate the general public on the need for extreme caution with the use of electricity!

YEAR	TOTAL NETWORK RECTIFIED
2014	199
2015	87
2016	801
2017	3048



(NEMSA)







River Bank erosion and reported sand dredging activities in Otamiri, Imo State, and Amechi village, Enugu State, endangering transmission line towers.



Dangerously tilted H-Pole at Adebowale Junction, Ondo Road, Akure, Ondo State.





SAFETY TIPS FOR THE RAINY SEASON:

- Avoid contact with electric poles, tv antenna poles, conductors and other electrical equipment installed in the open, during rainfall
- Avoid staying under trees and tall objects during thunderstorms
- Avoid climbing masts during rainfall/thunderstorms
- Avoid power cables and metallic objects during rainfall
- Wear rubber sole shoes always when on wet grounds
- Report any fallen electric poles or conductors to the nearest electricity utility company or to NEMSA office nearest to you.



