



"SAFETY RANKING OF DISCOS & TCN IN THE POWER SECTOR"

MAY 2018 RANKING

at the Honourable Minister of Power, Works & Housing's Monthly Sectoral Meeting with Operators of The Power Sector on Monday, 11th June, 2018 Venue: Mando Transmission Station, Kaduna Host: Kaduna Electricity Distribution Company

Engr. Peter .O. Ewesor Managing Director/CEO & Chief Electrical Inspector of the Federation





Many of the accidents that occur in the power

industry can be attributed to these major factors:

(i) System Protection Equipment Failures;

> (ii) In some cases, total absence of protection devices.

> > (iii)Poor Terminations , poor maintenance of Ageing Networks, Right-of-way issues.

(iv) Poor Response to Monitored Networks & use of substandard materials.

> (v) Non adherence to safety rules, and regulations .

(vii) Vandalism

(**Vi**) Inadequate knowledge and Ignorance on the part of operators/consumers/public.

Operators of the Power Sector to address these urgently.



(NEMSA)



RANKING CRITERIA

DESCRIPTION	EVENT	SCORES
I. TOTAL ACCIDENTS	NOT SCORED	NOT SCORED
II. NO. OF FATALITIES	0	40
III. NO. OF MAJOR INJURIES	0	25
IV. NO. OF BAD NETWORKS RESOLVED	>9	25
V. REPORTING COMPLIANCE	4	10
		100

Response	Scores
4	10
3	8
2	6
1	4
0	0

Fatalities (Dea	<u>ths)</u>
No. of Fatalities	Scores
0	40
1 - 2	32
3 – 4	24
5 – 6	16
7 – 8	8
9 & Above	0
2015 DACELINE	CTUDV.

2015 BASELINE STUDY: Average Deaths/month = 9.5 (10)

Major Injuries										
No. of Persons with Major Injuries	Scores									
0	25									
1 – 2	20									
3 – 4	15									
5 – 6	10									
7 – 8	5									
9 & Above	0									
2015 BASELINE STUDY: Not Available										

 No. Resolved
 Scores

 9 & Above
 25

 7 - 8
 20

 5 - 6
 15

 3 - 4
 10

 1 - 2
 5

 0
 0

NETWORK RESOLVED

2015 BASELINE STUDY: Average/ month = 7.5 (8)

Criterion for Network Monitored/Resolved to be revised upwards

6	RICITY MANAGE	4
AN ELE	THE	ENIOL
LIGER	NEMSA	SADING FR
	AGENCY	

(NEMSA)



NE	MSA 🍣 /														
× *	ENCY *	AW DATA		/	MONTH	: MAY	2	018	WEIGHTED SCORE						
S/No.	DISCO	ACCIDENTS	TOTAL NO. OF DEATHS [STAFF & 3RD PARTY]	NO. OF MAJOR INJURIES	NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	REPORTING COMPLIANCE		DEATHS [STAFF & 3RD PARTY]	MAJOR INJURIES	BAD NETWORKS RESOLVED	REPORTING COMPLIANCE	TOTAL	RANKING		
1	ABUJA	0	0	0	2	4		40	25	5	10	80	5		
2	BENIN	0	0	0	9	4		40	25	25	10	100	(1)		
3	EKO	2	2	0	0	4		32	25	0	10	67	7		
4	ENUGU	0	0	0	20	4		40	25	25	10	100	(1)		
5	IBADAN	0	0	0	5	4		40	25	15	10	90	3		
6	IKEJA	2	2	0	9	4		32	25	25	10	92	2		
7	JOS	3	3	1	3	4		24	20	10	10	64	8		
8	KADUNA	2	2	0	10	4		32	25	25	10	92	2		
9	KANO	1	1	0	11	4		32	25	25	10	92	2		
10	PORT HARCOURT	0	0	0	11	4		40	25	25	10	100			
11	YOLA	0	0	0	4	4		40	25	10	10	85	4		
12	TCN	0	0	0	0	4		40	25	0	10	75	6		
	TOTAL	10	10	1	84										

Note: Discos should rectify defective networks reported to them by NEMSA as a priority. Notification by Discos to NEMSA for verification should be weekly, rather than waiting till end of the month.



(NEMSA)

Compliance Record on Disconnection of Structures/Premises under or within Right-of-Way of Power Lines

S/No.	DISCO	TOTAL PREMISES/STRUCTURES DISCONNECTED	TOTAL PREMISES/STRUCTURES DEMOLISHED	RANKING
1	ABUJA	0	0	LAST
2	BENIN	27	0	3
3	ЕКО	0	0	LAST
4	ENUGU	0	0	LAST
5	IBADAN	468	0	
6	IKEJA	0	0	LAST
7	JOS	91	0	2
8	KADUNA	11	5	4
9	KANO	0	0	LAST
10	PORT HARCOURT	0	0	LAST
11	YOLA	0	0	LAST
	TOTAL	597	5	

Notes:

1. Compliance by Discos to disconnect premises/buildings/structures under and within right-of-way of power lines has been unsatisfactory.

2. Discos are to note that they will be liable should electrical accidents occur in premises/buildings/structures which are under and/or within right-of-way of power lines and which the Discos are supplying electricity to.



(NEMSA)



DISCOS & TCN RANKING TREND IN 2018

S/N o.	DISCO	JAN	FEB	MARCH	APRIL	MAY	JUNE	JULY	AUG	SEPT	ОСТ	NOV	DEC	YTD
1	ABUJA	1	4	2	8	5								7
2	BENIN	5	3	3	1	1								4
3	EKO	1	1	3	6	7								6
4	ENUGU	1	3	1	5	1								2
5	IBADAN	8	2	1	7	3								8
6	IKEJA	2	4	1	2	2								2
7	JOS	6	1	3	5	8								9
8	KADUNA	1	1	6	3	2								4
9	KANO	3	1	4	4	2								5
	PORT HARCOURT	4	2	1	1	1								
11	YOLA	1	3	1	3	4								3
12	TCN	7	5	5	6	6								10



(NEMSA)



YEAR 2018 CUMULATIVE STATISTICS

MONTH MAY 2018	TOTAL NO. OF ACCIDENTS WITH FATALITIES	TOTAL NO. OF FATALITIES [STAFF & 3RD PARTY]		NO. OF ACCIDENTS NO. OF WITH ONLY INJURE INJURIES		PERSONS)	OTHER NON- DISCO/TCN ELECTRICAL DEATHS	NO. OF EXPLOSIONS / FIRES	NO. OF VEHICULAR ACCIDENTS	NO. OF ENVIRONMENTAL ACCIDENTS	TOTAL LOST MAN- HOURS	NO. OF BAD NETWORKS REPORTED FOR THE MONTH	YEAR-TO- DATE NO. OF BAD NETWORKS REPORTED	YTD NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	RESPONSE TO NEMSA REPORTS IN WEEKS
		STAFF	3 RD PARTY		STAFF	3 RD									
ABUJA	1	0	2	3	2	PARTY 3	3	0		0			0	79	
BENIN	5	1	4	0	0	0	0	0		0			211	71	
ЕКО	3	0	3	0	0	0	0	0	0	0			53		
ENUGU	1	1	0	0	0	0	0	0		0			106		
IBADAN	4	0	7	1	0	2	0	0		0			51	36	
IKEJA	2	0	2	6	6	0	0	0	3	0			974	389	
JOS	7	3	4	2	1	1	1	0		0			406	94	
KADUNA	6	2	4	1	0	5	0	0		0			67	66	
ΚΑΝΟ	7	2	5	3	1	2	0	0		0			44	55	
PORT HARCOURT	0	0	0	0	0	0	0	0		0			75	51	
YOLA	2	1	1	0	0	0	4	0		0			122	46	
TCN	0	0	0	0	0	0	0	0		0			0	0	
YEAR TOTAL	38	10	32	16	10	13	8	0	3	0			2109	1014	





Operators of the Power Sector to note: Zero target for Electrocutions nationwide.

Discos are encouraged to report domestic electrocutions not directly connected with their networks, for information only. This will not count against their ranking.

Discos to intensify efforts at:

(i) revamping/calibrating their protection schemes & equipment

(ii) rectifying defective networks to prevent electrical accidents and reduce technical losses. [iii] educating the general public on the need for extreme caution with using electricity!




(NEMSA)



Unsafe Installations in Discos Networks



Pieces of concrete used to support conductors and multiple joints on HT lines at Opebi Road by Osho Street (Link Rd) Junction, Ikeja. [Ikeja Electric]



Pieces of concrete removed but network remains unsafe with several joints over the major road at Opebi Road by Osho Street (Link Rd) Junction, Ikeja [Ikeja Electric]





SAFETY TIPS

- Do not build structures or carry out activities under power lines
- Avoid contact with electric poles, Tv antenna poles, conductors and other electrical equipment installed in the open.
- Avoid staying under trees with conductors running over such trees.
- Avoid climbing masts constructed close to power lines.
- Avoid power cables and metallic objects.
- Wear rubber sole shoes always when on wet grounds.
- Report any fallen electric poles or conductors to the nearest electricity utility company or to NEMSA office nearest to you. Do not attempt to touch these.



