



"SAFETY RANKING OF DISCOS & TCN IN THE POWER SECTOR" JANUARY 2019 RANKING

by

Engr. Peter .O. Ewesor Managing Director/CEO & Chief Electrical Inspector of the Federation

NEMSA No. 4, Dar es Salaam Crescent, Off Aminu Kano Crescent, Wuse II, Abuja, Nigeria. www.nemsa.com.ng





Many of the accidents that occur in the power

industry can be attributed to these major factors:

(i) System Protection Equipment Failures;

> (ii) In some cases, total absence of protection devices.

(iv) Poor Response to Monitored Networks & use of substandard materials.

> (v) Non adherence to safety rules, and regulations .

(iii)Poor Terminations , poor maintenance of Ageing Networks, Right-of-way issues.

(**Vi**) Inadequate knowledge and Ignorance on the part of operators/consumers/public.

(vii) Vandalism

Operators of the Power Sector to address these urgently.



(NEMSA)



RANKING CRITERIA

DESCRIPTION	EVENT	SCORES
I. TOTAL ACCIDENTS	NOT SCORED	NOT SCORED
II. NO. OF FATALITIES	0	40
III. NO. OF MAJOR INJURIES	0	25
IV. NO. OF BAD NETWORKS RESOLVED	>9	25
V. REPORTING COMPLIANCE	4	10
		100

Response	Scores
4	10
3	8
2	6
1	4
0	0

Fatalities (Dea	<u>ths)</u>								
No. of Fatalities	Scores								
0	40								
1 - 2	32								
3 – 4	24								
5 – 6	16								
7 – 8	8								
9 & Above	0								
2015 DASELINE	CTUDV.								

2015 BASELINE STUDY: Average Deaths/ month = 9.5 (10)

Major Injuries	
No. of Persons with Major Injuries	Scores
0	25
1 – 2	20
3 – 4	15
5 – 6	10
7 – 8	5
9 & Above	0
2015 BASELINE ST Not Available	-

<u>NETWORK RESOLVED</u>										
No. Resolved	Scores									
9 & Above	25									
7 – 8	20									
5 – 6	15									
3 – 4	10									
1 - 2	5									
0	0									

NETWORK DECOUVE

2015 BASELINE STUDY: Average/ month = 7.5 (8)

Criterion for Network Monitored/Resolved to be revised upwards



(NEMSA)



RAW DATA MONTH: JANUARY 2019 WEIGHTED SCORE													
S/No	DISCO	TOTAL ACCIDENTS WITH DEATHS	TOTAL NO. OF DEATHS [STAFF & 3RD PARTY]	NO. OF MAJOR INJURIES	NO. OF BAD NETWORKS RESOLVED BY DISCO / TCN	REPORTING COMPLIANCE		DEATHS [STAFF & 3RD PARTY]	MAJOR INJURIES	BAD NETWORKS RESOLVED	REPORTING COMPLIANCE	TOTAL	RANKING
1	ABUJA	0	0	0	2	4		40	25	5	10	80	5
2	BENIN	0	0	0	10	4		40	25	25	10	100	(1)
3	EKO	1	1	0	12	4		32	25	25	10	92	3
4	ENUGU	1	1	1	30	4		32	20	25	10	87	4
5	IBADAN	0	0	0	16	4		40	25	25	10	100	(1)
6	IKEJA	0	0	0	0	4		40	25	0	10	75	6
7	JOS	0	0	0	12	4		40	25	25	10	100	(1)
8	KADUNA	0	0	2	28	4		40	25	25	10	100	(1)
9	KANO	0	0	0	27	4		40	25	25	10	100	$\bigcirc 1$
10	PORT HARCOURT	0	0	0	12	4		40	25	25	10	100	
11	YOLA	0	0	0	8	4		40	25	20	10	95	2
12	TCN	0	0	0	0	4		40	25	0	10	75	6
	TOTAL	2	2	3	157		5.						

Note: Discos should rectify defective networks reported to them by NEMSA as a priority. Notification by Discos to NEMSA for verification should be weekly, rather than waiting till end of the month.



(NEMSA)

Compliance Record on Disconnection of Structures/Premises under or within Right-of-Way of Power Lines

S/No.	DISCO	TOTAL PREMISES/STRUCTURES DISCONNECTED	TOTAL PREMISES/STRUCTURES DEMOLISHED	RANKING
1	ABUJA	0	0	LAST
2	BENIN	10	0	2
3	EKO	0	0	LAST
4	ENUGU	0	0	LAST
5	IBADAN	5	0	3
6	IKEJA	0	0	LAST
7	JOS	26	0	
8	KADUNA	0	0	LAST
9	KANO	0	0	LAST
10	PORT HARCOURT	0	0	LAST
11	YOLA	0	0	LAST
	TOTAL	41	0	

Notes:

- 1. Compliance by Discos to disconnect premises/buildings/structures under and within right-of-way of power lines has been unsatisfactory.
- 2. Discos are to note that they will be liable should electrical accidents occur in premises/buildings/structures which are under and/or within right-of-way of power lines and which the Discos are supplying electricity to.



(NEMSA)



DISCOS & TCN RANKING TREND IN 2019

S/N o.	DISCO	JAN	FEB	MARCH	APRIL	MAY	JUNE	JULY	AUG	SEPT	ОСТ	NOV	DEC	YTD
1	ABUJA	5												5
2	BENIN	1												(1)
3	EKO	3												3
4	ENUGU	4												4
5	IBADAN	1												
6	IKEJA	6												6
7	JOS	1												(1)
8	KADUNA	1												(1)
9	KANO	1												1
10	PORT HARCOURT	1												
11	YOLA	2												2
12	TCN	6												6





Operators of the Power Sector to note: Zero target for Electrocutions nationwide.

Discos are encouraged to report domestic electrocutions not directly connected with their networks, for information only. This will not count against their ranking.

Discos to intensify efforts at:

(i) revamping/calibrating their protection schemes & equipment

(ii) rectifying defective networks to prevent electrical accidents and reduce technical losses. [iii] educating the general public on the need for extreme caution with using electricity!





SAFETY TIPS

- Do not build structures or carry out activities under power lines
- Avoid contact with electric poles, Tv antenna poles, conductors and other electrical equipment installed in the open.
- Avoid staying under trees with conductors running over such trees.
- Avoid climbing masts constructed close to power lines.
- Avoid power cables and metallic objects.
- Wear rubber sole shoes always when on wet grounds.
- Report any fallen electric poles or conductors to the nearest electricity utility company or to NEMSA office nearest to you. Do not attempt to touch these.



