

MONTHLY RETURNS ON ACCIDENT INVESTIGATED

AREA INSPECTORATE FIELD OFFICE: AKURE

MAY 2019

S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION
1	30-05-2019	Electrical Accident that claimed the life of Mr. Ojo Olusola Michael, an official of BEDC.
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		

16

17

NEMSA/TS&IS/0007

REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES
BEDC	28-05-2019/28-05-2019	1

INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES
--	--	Engr. Quadry J.A, Engr. B.O Fayose, Oladele O.O, Igwilo I.A	--

ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME
Visited site; Investigated the accident; Presently writing the report	1. Mr Ariyo Ebenezer 2. Mr. Dauda Oladimeji 3. Mr. Abegunde Segun	--

RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
Adequate safety precaution should be taken before embarking on any maintenance on the network.

Adequate safety precaution should be taken before embarking on any maintenance on the network.