

**NEMSA/TS&IS/0007**

**MONTHLY RETURNS ON ACCIDENT INVESTIGATED**

**AREA INSPECTORATE FIELD OFFICE: ENUGU**

S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
1	24/07/2019	ELECTROCUTION	ELECTRIC SHOCK	ENUGWU-AGIDI, ANAMBRA STATE	EEDC	OPARAKU MODESTUS	15/07/2019	ONE(1)	NONE	NONE	OPARAKU MODESTUS	UNSAFE ELECTRICAL WIRING	NONE	MRS. IFEOMA OKONKWO & MRS. OBIAJULU OKOYE (FAMILY MEMBERS OF DISEASED)	REPORTED TO EEDC	CLEAR VEGETATION ALONG LINE AND REHABILITATE LINE WITH STANDARD MATERIALS

17

*PLEASE SEE PICTURES ATTACHED*

19

20