

**NEMSA/TS&IS/0007**

MONTHLY RETURNS ON ACCIDENT INVESTIGATED																
AREA INSPECTORATE FIELD OFFICE: ENUGU																
S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
1	26/06/2019	ELECTROCUTION	ELECTRIC SHOCK	EZINIFITE, ANAMBRA STATE	EEDC	OPARAKU MODESTUS	23/06/2019	ONE(1)	NONE	NONE	OPARAKU MODESTUS	NEGLEGENCE AT SUB STATION	NONE	MT EMMA OFORMA		RESTRICT ACCESS TO SUBSTATION BY UNAUTHORIZED PERSONS
2	28/06/2019	ELECTROCUTION	ELECTRIC SHOCK	AWADA, OBOSI, ANAMBRA STATE	EEDC	OPARAKU MODESTUS	25/06/2019	ONE (1)	NONE	NONE	OPARAKU MODESTUS	INADEQUATE CLEARANCE OF LINE TO GROUND	NONE	MR PC EKE & MR KENNEDY UBA		LINE CLEARANCE SHOULD BE IMPROVED
3																

16  
17  
*PLEASE SEE PICTURES ATTACHED*

19  
20