

**NEMSA/TS&IS/0007**

**MONTHLY RETURNS ON ACCIDENT INVESTIGATED**

**AREA INSPECTORATE FIELD OFFICE: JOS - AUGUST 2019.**

S/N	DATE OF INVESTIGATION	ACCIDENT DESCRIPTION	ACCIDENT TYPE	LOCATION	DISCO	REPORTED BY	DATE REPORTED/OCCURRED	FATALITIES	INJURIES	HISTORICAL INCIDENT (If Any)	INVESTIGATED BY	POSSIBLE ROOT CAUSES	ACTIONS TAKEN	DETAILS OF EYE WITNESSES (CONTACTS)	FOLLOWUP ACTIONS (DATE) & OUTCOME	RECOMMENDATIONS MADE TO ELIMINATE SURFACE & ROOT CAUSES
1	19/08/2019	DIRECT CONTACT WITH 33KV ENERGISED LINE DURING POLE ERECTION	ELECTROCUTION	BAKIN KOGI COMMUNITY NASARAWA LGA NASARAWA STATE	AEDC	AEDC	15TH AUG 2019/11TH AUG.2019	2	NIL	NIL	ENGRS G.D NANJWAN& D.D BABA	CONDUCTIVE ELECTRIC POLE IN CONTACT WITH ENERGISED 33KV POWERLINE.	INVESTIGATION WAS CARRIED OUT.	COMMUNITY LEADER(MAI UNGWA),SHOP OWNER BY ACCIDENT SCENE IBRAHIM,ABDUL LAHI A.- RESIDENT	SENSITIZATION OF PUBLIC ON ILLS OF ELECTRICITY DANGERS & CONSEQUENCES,USE OF PPE ETC (AEDC)	THE NPF & NSCDC SHOULD BE USED BY AEDC FOR ARREST AT ALL TIMES WHERE UNAUTHORISED PERSONNEL ARE SIGHTED DOING WORK ON THE NETWORK

16

17

*PLEASE SEE PICTURES ATTACHED*

19

20